

Performance Up/Down Shift Points

% TPS	MPH					
	1->2	2->3	3->4	2->1	3->2	4->3
0.0	7	13	18	7	7	16
6.3	7	13	18	7	12	17
12.5	7	15	18	7	12	18
18.8	10	18	26	7	12	18
25.0	12	24	32	7	12	18
31.3	17	32	42	7	13	20
37.5	21	38	47	7	15	24
43.8	24	42	102	7	18	30
50.0	26	45	102	7	21	36
56.3	27	48	102	7	26	97
62.5	29	51	102	7	35	97
68.8	29	55	102	7	43	97
75.0	29	57	102	19	47	97
81.3	29	57	102	19	47	97
87.5	29	61	102	19	47	97
93.8	32	62	102	19	51	97
100	32	62	102	19	60	97

Manual Mode Up/Down Shift Points

% TPS	MPH					
	1->2	2->3	3->4	2->1	3->2	4->3
0.0	7	13	18	7	12	18
6.3	7	13	20	7	12	18
12.5	7	15	22	7	12	18
18.8	10	18	27	7	12	18
25.0	12	24	32	7	12	18
31.3	16	30	42	7	13	20
37.5	18	36	47	7	15	24
43.8	20	38	53	7	16	27
50.0	22	43	61	7	18	31
56.3	24	45	65	7	22	34
62.5	26	47	70	7	24	38
68.8	28	52	88	7	30	44
75.0	29	55	109	7	32	53
81.3	29	55	109	7	32	104
87.5	29	57	109	7	157	104
93.8	32	63	109	19	157	104
100	32	63	109	19	60	104

Kickdown Mode Shift RPM Thresholds Vs. Mode

Shift	Mode	
	Hot	Cold
1->2	5500	5500
2->3	5000	5000
3->4	5400	540

Kickdown Normal Mode Shift RPM Thresholds

Shift	RPM
1->2	5500
2->3	5000
3->4	5600

Kickdown Mode Up/Down Shift Points

Shift	MPH		
	Normal	Hot	Cold
1->2	32	32	32
2->3	60	60	60
3->4	102	102	102
2->1	21	21	21
3->2	62	62	62
4->3	102	102	102