

ProMotion Performance Products, Inc.
 4766 NE 12th Ave
 Fort Lauderdale, FL 33334
 954-771-5575 / 954-771-5964 fax

Invoice #
10306

Ship To

S/N	P.O. No.	Terms	Rep	Ship	Via
41969		Credit Card	Wally	3/29/2007	CPU
Qty.	Item Code	Description	Price Ea	Amount	
		020 Unit ReFresh			
1	T56CSK	T56 Carbon PARTIAL Synchro Kit	175.50	175.50	
1	12363	T56 Front Input Retainer Seal	4.50	4.50	
1	1300-044-019	T56/GM Rear Seal	6.00	6.00	
1	M88048	T5 - 4 Cyl / T45 / T56 Input Bearing or 8.8" & 9" Small Pinion Bearing / Cone	12.90	12.90	
1	BR16	T56 Input Pkt Brg & Race also fits C/S Rear Brg	18.40	18.40	
3	1351-093-001	3-4 Sync keys	0.75	2.25	
2	1386-156-002	T56 Rev 5/6 Sync Spring	2.03	4.06	
4	1386-235-001	T45/T56 1-4 Fork Pads	1.00	4.00	
2	1386-235-002	T45/T56 5-6 & Reverse Fork Pads	0.35	0.70	
2	1386-235-001	T45/T56 1-4 Fork Pads	1.00	2.00	
1	GFT56049	T5/T45/T56 fits 3/4 Billet Key (set of 3)	99.00	99.00	
	LABOR	Labor	250.00	250.00	
		Subtotal		579.31	
	W	CHECK OUT OUR NEW WEB SITE @ www.promotionpowertrain.com			
	OIL	NOTICE ! This Unit DOES NOT Contain Oil. After Installation, fill to the bottom of the Fill Plug Hole with DEXRON/MERCON ATF III			
	REPAIR	NOTICE ! Repairs performed on this Transmission are covered by a 60 day LIMITED WARRANTY, NO WARRANTY on broken gears, abuse, SYNCHRO FAILURE DUE TO BAD CLUTCH DISENGAGEMENT, R & R or if unit is run low on oil or is dissembled.			
		Sales Tax	6.00%	34.76	

It's been a pleasure working with you!	Total	\$614.07
	Payments/Credits	\$0.00
	Balance Due	\$614.07

All returns must have our prior approval and may be subject to a 15% restocking fee. No returns after 15 days or on special orders.