


Without connection to HP Tuners Monitoring using only LogWorks



This is an intermediary step.

- It relies on cannibalizing the existing narrowband sensor that is removed and replaced by the wideband sensor – cut the cable and use the stock connector. Alternatively, buy an O2 extension harness from Casper Electronics.
- It allows the LC-1 to be tested independently of HP Tuners. Any issues caused by HP Tuners connection are eliminated.
- However, there is no way of checking the wideband against the narrowband readings.
- The narrowband readings can be checked by logging with VCM Scanner, as normal.

This wiring diagram is for the new Innovate configuration with 6 wires, instead of the old 7 wire connection

Serial connection
to LogWorks

