



**FREE SHIPPING**  
**AVAILABLE ON ORDERS**  
**OVER \$100.00 (USA)**

Tick Performance, Inc. Invoice for Order #27711

179 Thunder Rd  
 Mount Airy NC 27030-2545

### Billing Details

paul carpenter  
 3113 sandy circle  
 haines city, Florida 33844  
 United States  
 Phone: 863 421-6385  
 Email: pcarpenter5@tampabay.rr.com

### Shipping Details

paul carpenter  
 3113 sandy circle  
 haines city, Florida 33844  
 United States  
 Phone: 863 421-6385

**Order:** #27711  
**Payment Method:** PayPal (\$1,349.99)

**Order Date:** 23rd Dec 2014  
**Shipping Method:** Free Shipping

### Order Items

Qty	Code/SKU	Product Name	Price	Total
1	TICKL2FB	Tick Performance Level 2 Upgraded T56 Rebuild (600RWTQ) for 93-02 Camaro & Firebird	\$1,349.99 USD	\$1,349.99 USD
		New Bearings:	No	
		Upgrade to Viper 2nd Gear:	No	
		Upgrade to Viper Mainshaft:	No	
		Paint or Powdercoat:	No, standard degrease only	
		Bungs & Sprayers Installed:	No	
		Faceplating (Race Only):	No	

Subtotal: \$1,349.99 USD

Shipping: \$0.00 USD

**Grand Total: \$1,349.99 USD**

### Comments

This transmission/car has 50,000 miles and the unit has no known issues....just upgrading now that the car has 505 ft lbs at the wheels.



**FREE SHIPPING**  
AVAILABLE ON ORDERS  
OVER \$100.00 (USA)

Tick Performance, Inc. Invoice for Order #28097

179 Thunder Rd  
Mount Airy NC 27030-2545

### Billing Details

**paul carpenter**  
3113 sandy circle  
haines city, Florida 33844  
United States  
Phone: 863 421-6385  
Email: pcarpenter5@tampabay.rr.com

### Shipping Details

**paul carpenter**  
3113 sandy circle  
haines city, Florida 33844  
United States  
Phone: 863 421-6385

**Order:** #28097  
**Payment Method:** Paying Manually (\$794.96)

**Order Date:** 13th Jan 2015  
**Shipping Method:** None

### Order Items

Qty	Code/SKU	Product Name	Price	Total
1	1386-086-004	Tremec #126 5th Drive Gear (F-Body & Viper)	\$164.99 USD	\$164.99 USD
1	1386-590-003	Tremec #117 5th/6th Synchronizer Assembly (F-Body & Cobra & Viper)	\$99.99 USD	\$99.99 USD
1	1386-590-002	Tremec #14 3rd/4th Synchronizer Assembly (F-Body & Cobra & Viper)	\$109.99 USD	\$109.99 USD
1	T56CBK	Premium T56 Complete Bearing Kit	\$169.99 USD	\$169.99 USD
1	LABOR	REM Polish Transmission Internals	\$250.00 USD	\$250.00 USD
			Subtotal:	\$794.96 USD
			Shipping:	\$0.00 USD
			<b>Grand Total:</b>	<b>\$794.96 USD</b>

### Comments

THESE PARTS NEEDED IN ADDITION TO YOUR REBUILD CURRENTLY UNDERWAY. OUR BUILDER NOTED THE FOLLOWING:

"Fifth gear has damage on the engagement teeth and needs replacing. The 5/6 and 3/4 Synchronizers have damage to the engagement teeth and must be replaced. We recommend new bearings."

REM POLISH ADDED AT CUSTOMER'S REQUEST


Tick Performance, Inc.  
to pcarpenter5@tampabay.rr.com

Tue, Dec 23 8:35 AM

Your Tick Performance, Inc. Order Confirmation (#27712)

## Thanks for Your Order

---

 Your order ID is #27712. A summary of your order is shown below. To view the status of your order click here.

### Shipping Address

paul carpenter  
3113 sandy circle  
haines city, Florida 33844  
United States  
863 421-6385

### Billing Address

paul carpenter  
3113 sandy circle  
haines city, Florida 33844  
United States  
863 421-6385

### Order Instructions/Comments

Does the clip for connecting the quick disconnect come with this unit? If not where can I get one? Thanks, Paul

### Your Order Contains...

Cart Items	SKU	Qty	Item Price	Item Total
GM Slave Cylinder & Throwout Bearing for 98-02 Camaro& Firebird (LS1)	24264182	1	\$138.99 USD	\$138.99 USD
<b>Subtotal:</b>				<b>\$138.99 USD</b>
<b>Shipping:</b>				<b>\$0.00 USD</b>
<b>Grand Total:</b>				<b>\$138.99 USD</b>

Tick Performance, Inc.  
<http://www.tickperformance.com/>

---