

Steering - Control Arm Bracket Kit for Camber Adjustment

Bulletin No.: 05-08-61-001

Date: January 04, 2005

INFORMATION

Subject:

Availability of Upper Control Arm Bracket Service Kit for Camber Adjustments

Models:

2004-2005 Cadillac CTS-V

Minor road hazards can create inputs into the front suspension that can result in changes to the front end alignments. This may create a need to adjust the camber, which may be out of the adjustable movement range.

DO NOT REPLACE THE CRADLE.

An upper control arm service kit has been released. The service kit will allow for greater negative camber adjustment.

Part Number	Description
88965464	Frt S/ABS Upr Bracket Kit

Parts are expected to be available from GMSPO on January 14, 2005.

Parts Information

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT
VOLUNTARY
TECHNICIAN
CERTIFICATION