

run	Labels	400	600	800	1000	1200	1400	1600	1800	2000	2200	2400	2800	Timing change
1st	0.32			97	100	118	113	111	118	123	123	123	125	0
2nd	0.32			105	101				129	127	136	126	124	2
3rd	0.32								125	124	125	127	129	2
4th	0.32			105	107	129	115	125	131	131	135	133	134	1
5th	0.32				118	132	126	120	129	129	130	133	127	-1